



# quick start guide

## SuperDos 45


0.25 - 45 gpm 5 - 100 psi  
57 - 10000 l/h 0,4 - 6,9 bar

\*5% model has maximum operating pressure of 80 psi (5,5 bar)  
\*\*\*NOTE\*\*\* Remote injection is NOT recommended for use with 5% model



**0.25 - 45 gpm 5 - 100 psi  
57 - 10000 l/h 0,4 - 6,9 bar**

**\*5% model has maximum operating pressure of 80 psi (5,5 bar)**  
**\*\*\*NOTE\*\*\* Remote injection is NOT recommended for use with 5% model**



**0.25 - 45 gpm 5 - 100 psi  
57 - 10000 l/h 0,4 - 6,9 bar**

**\*5% model has maximum operating pressure of 80 psi (5,5 bar)**  
**\*\*\*NOTE\*\*\* Remote injection is NOT recommended for use with 5% model**



**Hydro Systems**  
3798 Round Bottom Road  
Cincinnati, OH 45244

**Phone** 513.271.8800  
**Toll Free** 800.543.7184  
**Fax** 513.271.0160  
**Web** [hydrosystemsco.com](http://hydrosystemsco.com)